

Inspection Photos

API: 043-06212

Operator: INCREMENTAL OIL & GAS

Inspection Date: 2/9/2021



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06212 | Date: 2/9/2021

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06212 | Date: 2/9/2021

Inspection Photos



Photo 2. Facing northwest toward the interim reclamation area. Vegetation is well established in the interim area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06212 | Date: 2/9/2021

Inspection Photos



Photo 3. There is undesirable weed debris accumulated along the northeast fence. The weed debris needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06212 | Date: 2/9/2021