

Grizzly Operating Platzer Location # 335127

Feb 11, 2021 at 1:16:12 PM
39.494923,-107.647438 ±4.24m
COGCC



location

Feb 11, 2021 at 1:17:52 PM
39.494973,-107.647132 ±4.81m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Platzer Location # 335127

Feb 11, 2021 at 1:19:15 PM
39.494964,-107.646530 ±4.79m
COGCC



location

Feb 11, 2021 at 1:16:16 PM
39.494923,-107.647438 ±4.24m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Platzer Location # 335127

Dec 14, 2020 at 11:57:50 AM
39.494911, -107.646871 ±4.72m
COGCC



Previous inspection of lack of stabilization

Feb 11, 2021 at 1:18:37 PM
39.494994, -107.646880 ±4.82m
COGCC



Follow up inspection of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Platzer Location # 335127



Previous inspection of lack of stabilization



Follow up inspection of lack of stabilization



Grizzly Operating Platzer Location # 335127



Lack of stabilization




Lack of stabilization



Grizzly Operating Platzer Location # 335127



Lack of stabilization



Staining

