

Grizzly Operating Schirer Location # 335500

Feb 9, 2021 at 1:39:01 PM
39.493664,-107.642368 ±35.95m
COGCC



location

Feb 9, 2021 at 1:40:20 PM
39.493716,-107.642060 ±4.81m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Schirer
Location # 335500**



Location/Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Schirer
Location # 335500**



Previous inspection photo of lack of stabilization



Follow up inspection photo of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Schirer
Location # 335500**



Previous inspection photo of lack of stabilization



Follow up inspection photo of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
Schirer
Location # 335500**



Previous inspection photo of lack of stabilization



Follow up inspection photo of lack of stabilization

**Grizzly Operating
Schirer
Location # 335500**



Previous inspection photo of lack of stabilization



Follow up inspection photo of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources