

# Grizzly Operating Dommer Location # 335501

Feb 10, 2021 at 11:00:48 AM  
39.497715,-107.633185 ±4.75m  
COGCC



location

Feb 10, 2021 at 11:00:54 AM  
39.497715,-107.633185 ±4.75m  
COGCC



location

# Grizzly Operating Dommer Location # 335501

Feb 10, 2021 at 10:58:31 AM  
39.497302,-107.632734 ±4.75m  
COGCC



location

Feb 10, 2021 at 10:57:45 AM  
39.497260,-107.632479 ±4.78m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Grizzly Operating  
Dommer  
Location # 335501**



**Lack of stabilization from previous inspection**



**Lack of stabilization from follow up inspection**





**Grizzly Operating  
Dommer  
Location # 335501**



**Lack of stabilization from previous inspection**



**Lack of stabilization from follow up inspection**





**Grizzly Operating  
Dommer  
Location # 335501**

Feb 10, 2021 at 11:03:50 AM  
39.497819,-107.633164 ±4.78m  
COGCC



**Lack of stabilization**

Feb 10, 2021 at 11:04:44 AM  
39.497733,-107.633089 ±4.80m  
COGCC



**Lack of stabilization**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources