

# Grizzly Operating Geiski Location # 335120

Feb 10, 2021 at 11:37:07 AM  
39.500259,-107.630054 ±4.77m  
COGCC



location

Feb 10, 2021 at 11:37:13 AM  
39.500259,-107.630054 ±4.77m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

# Grizzly Operating Geiski Location # 335120

Feb 10, 2021 at 11:40:56 AM  
39.499824,-107.630152 ±4.79m  
COGCC



location

Feb 10, 2021 at 11:44:24 AM  
39.499992,-107.629508 ±4.76m  
COGCC



location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



# Grizzly Operating Geiski Location # 335120



**Lack of stabilization from previous inspection**



**Lack of stabilization from previous inspection**





# Grizzly Operating Geiski Location # 335120



**Lack of stabilization from follow up inspection**



**Lack of stabilization from follow up inspection**





# Grizzly Operating Geiski Location # 335120



**Lack of stabilization/ Lack of tracking controls from follow up inspection**



**Lack of stabilization/ Lack of tracking controls from follow up inspection**





**Grizzly Operating  
Geiski  
Location # 335120**

Feb 10, 2021 at 11:35:39 AM  
39.500849,-107.629598 ±29.24m  
COGCC



**Lack of stabilization/ Lack of tracking controls from  
follow up inspection**

Feb 10, 2021 at 11:35:43 AM  
39.500849,-107.629598 ±29.24m  
COGCC



**Lack of stabilization/ Lack of tracking controls from  
follow up inspection**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources