



40.1047, -108.85002, 5175.8ft, 208°
02/05/2021 09:30:46 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

A.C. McLaughlin JR 11

API: 05-103-05577

Inspection: 700405349



40.10468, -108.85008, 5178.1ft, 111°
02/05/2021 09:31:06 AM



40.10467, -108.85009, 5187.3ft, 342°
02/05/2021 09:35:42 AM



40.10438, -108.85026, 5190.7ft, 284°
02/05/2021 09:27:13 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tank.

A.C. McLaughlin JR 11

API: 05-103-05577

Inspection: 700405349



40.10443, -108.85037, 5183.7ft, 98°
02/05/2021 09:28:09 AM

