

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER-66S95W /36NWNE

Location ID: 335172

Network:Feb 12, 2021 at 11:53:09 AM MST
Local:Feb 12, 2021 at 11:53:09 AM MST



Photo #2898 from entrance to location.

Network:Feb 12, 2021 at 11:53:12 AM MST
Local:Feb 12, 2021 at 11:53:12 AM MST



Photo #2899 from entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC POTTER-66S95W /36NWNE

Location ID: 335172



Photo #2900 Rutting present on location due to lack of stabilization.



Photo #2901 Rutting present on location due to lack of stabilization.