

Inspection Photos
Location Name: Coalmont 3-13H
Location ID: 421227



Photo 1. Overview of location taken facing southwest.



Photo 2. No bradenhead access apparent.

