

Inspection Photos

Loc#324043

Operator: Terra

Insp#: 692403030

Insp Date: 2/10/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View into Well pad portion of Location to East.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#324043



Photo#2:
View over Location to East.



Photo#3:
Interim area.

February 10, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#324043