

Interim Reclamation and Stormwater Inspection

February 16, 2021

Operator: CONOCO PHILLIPS COMPANY- #19160

Location ID: 437846

Inspection Document #: 697502565

Arapahoe County, CO

SESW Section 13 T5S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 1. Drone aerial imagery illustrates the Operator has performed interim reclamation activities.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 2. Drone aerial imagery of the northwestern location. Scotch thistle was observed along the access road and western interim area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 3. Google Earth aerial imagery from 5/31/2018 illustrates the location disturbance areas.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 4. Photo taken from the entrance of location, facing South.



Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 5. Photo taken from the western access road, facing North. Photo illustrates Scotch thistle throughout the entire access road.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 6. Photo taken from the western access road, facing West. See comments under Photo 5.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 7. Photo taken from the northwestern interim reclamation area. Photo illustrates a mature Scotch thistle that appears to be pushed over. This was observed throughout the entire northwestern and western interim area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 8. Photo taken from the northwestern interim reclamation area, facing East. See comments under Photo 7.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502565

Inspection Photos

Location Name: State La Plata 5-65 13-15 /4AH

Location ID: 437846



Photo 9. Photo taken from the northwestern interim reclamation area, facing West. Photo illustrates the stormwater BMP area is in proper functioning condition.