

Inspection Photos

Loc#335646

Operator: Terra

Inspection Number: 692403048

Inspection Date: 2/11/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from entry Insert close up of rutting on site.

February 11, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough Loc#335646



Photo#2:
Debris weeds in BMPS.




Photo#3:
Debris weeds in BMPS.

February 11, 2021



Photo#4:
Undercutting of BMP on south Cut.

February 11, 2021



Photo#5:
Undercutting of BMP on south Cut.



Photo#6:
Undercutting of BMP on South Cut.

February 11, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#7:
Bypassing/undercutting of BMP on South
Cut.

Inspection Photos: Terra Clough Loc#335646



Photo#8:
View of terraced Southeast area of Cut Slope.

February 11, 2021



Photo#19:
View along North Cut Slope.