

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts:	<input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 697806 | Date: 11/28/1979 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 643479 | Date: 1/22/1996 |
| Doc #: 500162639 | Date: 4/7/1998 |
| Doc #: | Date: |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2142986 | Date: 8/1/1997 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Prior to 1996 inspection.

Pit Status Review Summary:

Based on records review and aerial imagery, any pits on location were replaced by a fiberglass tank prior to 1/22/1996 field inspection. Field inspections and 1997 pit inventory report document a 75bbl fiberglass tank on location. Associated well PA 5/4/2017. Pit Status has been changed to closed.

