

Inspection Photos
Location Name: Greasewood 09-19H
Location ID: 423607



Photo 1 – Wellhead, Unmarked Risers



Photo 2 – Tank Battery, Signs missing



Inspection Photos
Location Name: Greasewood 09-19H
Location ID: 423607



Photo 3 – Risers have been marked



Photo 4 – Production Equipment



Inspection Photos
Location Name: Greasewood 09-19H
Location ID: 423607



Photo 5 – Tank Battery Sign

Photo 6 – Signs have faded on Tanks



Inspection Photos
Location Name: Greasewood 09-19H
Location ID: 423607



Colorado Oil and Gas Conservation Commission
40.47975, -104.25939, 4629.8ft, 215°
02/16/2021 13:40:56

Photo 7 – Missing Capacity



Colorado Oil and Gas Conservation Commission
40.47956, -104.25927, 4608.3ft, 190°
02/16/2021 13:41:25

Photo 8 – Flare