

Inspection Photos

Loc#422211

Operator: Terra

Inspection Number: 692403054

Inspection Date: 2/12/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location to Northwest.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough NR Loc#422211



Photo#2:
Interim area.



Photo#3:
Entry into Well area.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough NR Loc#422211



Photo#4:
Stormwater area of concern, view South.



Photo#5:
Stormwater area of concern, view North.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough NR Loc#422211



Photo#6:
Area of concern on access road.



Photo#7:
Area. of concern on access road.

February 12, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Clough NR Loc#422211