

Caerus Piceance LLC
O1E
Location # 334939

Feb 22, 2021 at 10:20:13 AM
39.548471,-107.669502 ±3591.62m
COGCC



location

Feb 22, 2021 at 10:20:31 AM
39.472334,-107.614571 ±5.95m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
O1E
Location # 334939

Feb 22, 2021 at 10:20:50 AM
39.472276,-107.614468 ±4.86m
COGCC



location

Feb 22, 2021 at 10:21:06 AM
39.472276,-107.614468 ±4.86m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
O1E
Location # 334939

Feb 22, 2021 at 10:21:09 AM
39.472276,-107.614468 ±4.86m
COGCC



Location/ entrance

Feb 22, 2021 at 10:22:43 AM
39.472205,-107.613667 ±4.77m
COGCC



location/ Tank signage is TEP



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
O1E
Location # 334939

Feb 22, 2021 at 10:22:06 AM
39.472109,-107.613883 ±4.82m
COGCC



location/ Tank signage is TEP

Feb 22, 2021 at 10:26:43 AM
39.472154,-107.613616 ±4.77m
COGCC



location/ Tank signage is TEP



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
O1E
Location # 334939



Debris



Debris



Caerus Piceance LLC
O1E
Location # 334939



Debris



Debris



Caerus Piceance LLC
O1E
Location # 334939




Paraffin over running the bucket/ staining



Debris



Caerus Piceance LLC
O1E
Location # 334939



location/ unmarked bucket



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources