

Inspection Photos

2/19/2021

Operator: CHEVRON USA INC - 16700

Location ID: 314804

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 1: Photo taken from the northwest corner of the Location, facing west. Photo shows areas of the location where stormwater runoff has created a gully; stormwater and erosion control measures to protect/stabilize slopes and to allow for sediment laden-free stormwater discharge are missing, or insufficient. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 2: Continued from photo 1. Photo shows gully on northwest corner of the Location.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 3: Continued from photo 1. Photo shows gully on northwest corner of the Location. 6 foot measuring stick for reference.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 4: Photo shows cable debris observed next to the gully, on the northwest corner of the Location.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



20210219

Photo 5: Photo taken from the west end of the Location, facing northwest. Photo shows various wood debris observed on the slopes.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 6: Photo taken from the west end of the Location, facing southwest. . Photo shows stormwater and erosion control measures to protect/stabilize slopes and to allow for sediment laden-free stormwater discharge are missing, or insufficient.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 7: Photo of wellhead, signage and concrete based; Well shut-in



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804




Photo 8: Photo taken from the north end of the Location, facing east. Photos 8-10 provide an overview of the Location from east, south to west.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 9: See comments under photo 8.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 314804



Photo 10: See comments under photo 8.

