


## Inspection Photos

Location Name: CECIL USX A-66N64W /1SWSW

Location #: 302411



Colorado Oil & Gas Conservation Commission  
Weld  
+40.509996, -104.505504  
126° SE  
23-Feb-2021 15:18

**Photo #1**

**Cecil USX A 01-13 (05-123-29088) Wellsite**

**Temporarily Abandoned | TA**



Colorado Oil & Gas Conservation Commission  
Weld  
+40.511324, -104.506342  
89° E  
23-Feb-2021 15:47

**Photo #2**

**Cecil USX A 01-13, 01-14 Battery site**

**Abandoned: ALL Equipment Removed**