

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/23/2021

Submitted Date:

02/23/2021

Document Number:

696104382**FIELD INSPECTION FORM**

Loc ID 302411	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 13 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1001 NOBLE ENERGY WAY</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77070</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298535	WELL	TA	05/04/2020	OW	123-29088	Cecil USX A 01-13	TA

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Abandoned. ALL equipment has been removed.
 Abandoned Battery SE corner GPS coordinates: 40.511316 / -104.505726

Abandoned Centralized Battery formerly served 2 Location IDs.
 (302411, 306275).
 (Well(s): 2: Temporarily Abandoned | TA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	Battery Abandoned. Equipment removed.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment: Battery Abandoned. Equipment removed.						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: Battery Abandoned. Equipment removed.						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298535 Type: WELL API Number: 123-29088 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned: All Equipment Removed.
COGCC records indicate last production: 04/2016.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/04/2019 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: End Surf Csg Pressure: --

Comment: No record of Brhd test within last 12 months.
Submit current Brhd test.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
COGCC Inspection Report Summary: On TUE 02/23/2021 at approximately 15:18 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: CECIL USX A-66N64W /1SWSW Location ID: 302411 Well Name: Cecil USX A 01-13 API: 05-123-29088 Location County: Weld County, Colorado Weather: Mostly sunny, damp from prior storm. While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.511316 / -104.505726 Abandoned Centralized Battery formerly served 2 Location IDs. (302411, 306275). (Well(s): 2: Temporarily Abandoned TA). During this inspection, NO possible compliance issues were observed. This is a summary of the inspection report.	evinsb	02/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104383	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5359209