

Interim Reclamation and Stormwater Inspection

February 23, 2021

Operator: EDGE ENERGY II LLC- 10671

Location ID: 428546

Inspection Document #: 697502590

Weld County, CO

NWNE Section 16 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546



Photo 1. Photo taken of the pumpjack sign. Photo illustrates Operator has removed unused equipment previously observed on 10/28/2020.

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546



Photo 2. Photo taken from the wellhead, facing North. Photo illustrates stained soil from equipment.

Inspection Photos

Location Name: Black Hollow 8-67-16 #3H

Location ID: 428546



Photo 3. Photo taken from location, facing East. Photo illustrates unused equipment has not been removed per the previous corrective action inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502590

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546



Photo 4. Photo taken from location, facing North. Photo illustrates Operator has failed to install BBLS on tanks per the previous corrective action inspection.

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546



Photo 5. Photo taken from the southern interim reclamation area, facing West. Photo illustrates unmanaged Russian thistle weeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502590

Inspection Photos

Location Name: Black Hollow 8-67-16 #3H

Location ID: 428546



Photo 6. Photo taken from the western interim reclamation area, facing North. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502590

Inspection Photos

Location Name: Black Hollow 8-67-16 #3H

Location ID: 428546



Photo 7. Reference photo taken east of the location, facing North. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502590

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
Location ID: 428546



Photo 8. Overview photo taken east of the location, facing West. Photo illustrates the weedy interim reclamation areas, which are not reflective of reference areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502590