

## Inspection Photos

Location Name: James S Haley Trustee B #2 Flowline Release

Remediation No. 16137/ Spill ID: 478014



**Photo 1 – Impacted soils from daylighting of second spill on location.**



**Photo 2 – Spill area 9/25/2020 inspection – no impacted soils visible**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: James S Haley Trustee B #2 Flowline Release

Remediation No. 16137/ Spill ID: 478014



**Photo 3 –Soils stored on location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources