

Inspection Photos

Location Name: H. Huett Consolidation Release

Remediation No. 16135/ Spill ID: 478005 (CL)



Colorado Oil and Gas Conservation Commission
40.04357, -104.85482, 4902.5ft, 229°
02/22/2021 02:25:39 PM

Photo 1 – Spill excavation area. Stockpiled soils have been removed.



Colorado Oil and Gas Conservation Commission
40.04356, -104.8548, 4895.7ft, 150°
02/22/2021 02:25:43 PM

Photo 2 – Spill excavation area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: H. Huett Consolidation Release

Remediation No. 16135/ Spill ID: 478005 (CL)



Photo 3 – Stained soils visible on location outside of excavated area.



Photo 4 – Stained soils visible near/in pothole location.

