

Final Reclamation Inspection

February 23, 2021

Operator: ANADARKO E&P ONSHORE LLC - #2800

API: 05-123-31795

Inspection Document #: 697502594

Weld County, CO

NWNW Section 1 T8N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 1. Photo taken from the approximate entrance of location, facing East. Photo illustrates the establishment of desirable perennial vegetation; however, the location will remain in process until it meets Rule 1004 vegetative standards.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 2. Photo taken along the western location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 3. Photo taken along the western location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 4. Photo taken along the western location, facing Northeast. See comments under Photo 1.

Inspection Photos
Location Name: HOBART #8-67-1-4H
API: 05-123-31795



Photo 5. Photo taken from the approximate entrance of location, facing East. Photo illustrates reference vegetation (right of the red-dashed line) and the disturbance area (left of the red-dashed line).