

**Inspection Photos**  
**Location Name: State Antelope P-32 Pad**  
**Location ID: 432677**



Feb 24, 2021 at 11:52:26 AM  
+40.3626, -104.3423  
Weid  
Colorado Oil & Gas Conservation Commission

**Photo #1 Location**

**Inspection Photos**  
**Location Name: State Antelope P-32 Pad**  
**Location ID: 432677**



**Photo #2 Stained Soil**

**Photo #3 Leaking Master valve**

Inspection Photos  
Location Name: State Antelope P-32 Pad  
Location ID: 432677



Photo #4 Stained Soil/ Leaking master valve

Photo #5 Trash "jug"

Inspection Photos  
Location Name: State Antelope P-32 Pad  
Location ID: 432677



Photo #6 Trash "Tarp", Pit lid is not cover pit hole.

Photo #7 Trash "Rag"

**Inspection Photos**  
**Location Name: State Antelope P-32 Pad**  
**Location ID: 432677**



**Photo #8 Trash**

**Photo #9 Wells**