

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2021

Submitted Date:

02/25/2021

Document Number:

691201403

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202
Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
MacLaren, Joe		joe.maclaren@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Knop, Max	303-825-4822	MKnop@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477603	SPILL OR RELEASE	AC	08/10/2020		-	Peltier #2 Flowline	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Inspected Facilities

Facility ID: 477603 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: No Form 19 or Form 27 has been submitted since 8/6/2020.

Corrective Action: As per CA on Insp Document #691201366: Operator shall provide documentation of completed remedial actions within 45 days of the spill date. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples.

Date: 08/31/2020

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201404	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5360936