



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location sign.

API: 05-103-10112, 10524 to 10528, 10625 to 10627
Piceance Creek T35X-11G Inspection: 700405545



39.89102, -108.2512, 6929.1ft, 13°
02/24/2021 02:26:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Location.

API: 05-103-10112, 10524 to 10528, 10625 to 10627
Piceance Creek T35X-11G Inspection: 700405545



39.89107, -108.25096, 6927.7ft, 339°
02/24/2021 02:24:48 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Wells.

API: 05-103-10112, 10524 to 10528, 10625 to 10627
Piceance Creek T35X-11G Inspection: 700405545



39.89204, -108.25086, 6941.3ft, 322°
02/24/2021 02:31:45 PM



39.89156, -108.25064, 6931.8ft, 79°
02/24/2021 02:28:47 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Chemical & tank.

API: 05-103-10112, 10524 to 10528, 10625 to 10627
Piceance Creek T35X-11G Inspection: 700405545



39.8917, -108.25034, 6944.5ft, 86°
02/24/2021 02:29:26 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tank.

API: 05-103-10112, 10524 to 10528, 10625 to 10627
Piceance Creek T35X-11G Inspection: 700405545