

Inspection Photos
Facility Name: Parker #44-15
Remediation Project No. 13908/ Spill ID 464277 (CL)



Photo 1 – Remediation area; fencing around open excavation beginning to fall



Photo 2 – Remediation area; fencing around open excavation beginning to fall.



Inspection Photos
Facility Name: Parker #44-15
Remediation Project No. 13908/ Spill ID 464277 (CL)



Photo 3 – Extra fence material in open excavation



Photo 4 – Soils stored on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Facility Name: Parker #44-15
Remediation Project No. 13908/ Spill ID 464277 (CL)



Photo 5 – Surface staining visible outside of excavation area

