

# Inspection Photos

2/24/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915



**Photo 1:** Photo taken from the Location entrance. Photo shows signage that states a delayed IR 502.b variance has been approved on the Location. There are no records within the Location or well files that a 502.b delayed interim reclamation variance (per the NTO) has been submitted and approved for this Location.



Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335915



20210224

**Photo 2:** Photo taken from the east end of the Location, facing west. Photo shows Location entrance, tank battery and separator equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915



**Photo 3:** Photo taken from the west end of the Location, facing north. Photos 3-6 provide an overview of the Location from north, northeast, southeast to south. Photos show interim reclamation of areas not needed for production have not been performed on the Location.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335915



**Photo 4:** See comments under photo 3.





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335915



**Photo 5:** See comments under photo 3.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335915



**Photo 6:** See comments under photo 3.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources