

Inspection Photos

Location Name: LARAMIE ENERGY LLC Red Mountain Ranch /33-11 Pad

Location ID: 334525



Photo #2984 from entrance to location.



Photo #2985 from entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Red Mountain Ranch /33-11 Pad

Location ID: 334525



Photo #2986 Wellhead sign weathered and not legible.



Photo #2987 Flow line heating insulation open ended and not capped.