

Inspection Photos

Location Name: LARAMIE ENERGY LLC Red Mountain Ranch /4-6 Pad

Location ID: 334512



Photo #2988 from entrance to location.



Photo #2989 Multiple flow line heating insulation open ended and not capped.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Red Mountain Ranch /4-6 Pad

Location ID: 334512



Photo #2990 Multiple flow line heating insulation open ended and not capped.