

Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 324399

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324399



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the production areas from east, southeast, southwest to west. Photo also show areas where off Location vehicle traffic is observed on the eastern interim areas of the Location



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324399



Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324399



Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 324399



20210301

Photo 4: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 324399



Photo 5: Photo shows well head and signage.

