

Caerus Piceance LLC
I35
Location # 334919

Mar 2, 2021 at 10:52:16 AM
39.480371,-107.736971 ±42.25m
COGCC



location

Mar 2, 2021 at 10:58:17 AM
39.480197,-107.736938 ±4.79m
COGCC




location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
I35
Location # 334919

Mar 2, 2021 at 10:56:44 AM
39.480591,-107.736364 ±4.77m
COGCC



location

Mar 2, 2021 at 10:58:24 AM
39.480197,-107.736938 ±4.79m
COGCC



location/entrance



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
I35
Location # 334919

Mar 2, 2021 at 10:54:00 AM
39.480597,-107.736775 ±4.73m
COGCC



Sediment from location is being moved off of location from snow removal.

Mar 2, 2021 at 10:54:16 AM
39.480685,-107.736692 ±4.75m
COGCC



Sediment from location is being moved off of location from snow removal.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC

I35

Location # 334919



Sediment from location is being moved off of location from snow removal.



Sediment from location has been moved off of location from snow removal.

Caerus Piceance LLC
I35
Location # 334919

Mar 2, 2021 at 10:55:41 AM
39.480652,-107.736266 ±4.76m
COGCC



Sediment from location is being moved off of location from snow removal.

Mar 2, 2021 at 10:56:05 AM
39.480748,-107.736204 ±4.75m
COGCC



Sediment from location is being moved off of location from snow removal.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
I35
Location # 334919



**Sediment from location has been moved off of
location from snow removal.**