

Inspection Photos

3/1/2021

Operator: BERRY PETROLEUM COMPANY LLC

#10091

Location ID: 335585

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: BERRY PETROLEUM COMPANY LLC #10091
Location ID: 335585



Photo 1: Photo taken from the access road at the Location entrance. Photo shows unused equipment stored off the access road.

Inspection Photos
Operator Name: BERRY PETROLEUM COMPANY LLC #10091
Location ID: 335585



Photo 2: Photo taken from the southeast end of the Location, facing west. Photos 2-3 provide an overview of the Location entrance from southwest to west to north. Location shared between Caerus and Berry Petroleum. Photo also shows control measures to stabilize pad during wet conditions showing signs of degradation and disrepair; off-location sediment transport not observed at time of inspection, however pad stabilization and tracking issues becoming evident.

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC #10091

Location ID: 335585



Photo 3: See comments under photo 2.



Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC #10091

Location ID: 335585



Photo 4: Photo taken from the north end of the Location. Photo shows rock sock. Rock sock in disrepair and material has spilled onto Location; this is trash debris and requires removal.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC #10091

Location ID: 335585



Photo 5: Photo shows trash debris within tank containment BMP

Inspection Photos
Operator Name: BERRY PETROLEUM COMPANY LLC #10091
Location ID: 335585



Photo 6: Photo of wells and signage.

Inspection Photos
Operator Name: BERRY PETROLEUM COMPANY LLC #10091
Location ID: 335585



Photo 7: Photo shows example of marked anchors on the Location.

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC #10091

Location ID: 335585



Photo 8: Photo taken from the eastern interim areas of the Location, facing northeast. Photo shows vegetation on interim areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC #10091

Location ID: 335585



20210301

Photo 9: Photo taken from the south end of the Berry portion of the Location, facing west. Photo 9-11 provide an overview of the Location from west, northwest to northeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC #10091

Location ID: 335585



Photo 10: See comments under photo 9.



Inspection Photos
Operator Name: BERRY PETROLEUM COMPANY LLC #10091
Location ID: 335585



Photo 11: See comments under photo 9.

Inspection Photos
Operator Name: BERRY PETROLEUM COMPANY LLC #10091
Location ID: 335585



Photo 12: Photo of signage at the Berry portion of the production area.