

Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335766

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335766



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the Location from east, southeast, southwest to west. Photos also show control measures to stabilize production area and prevent off-location sediment transport during wet conditions has not been maintained in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335766



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335766



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335766



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335766



Photo 5: Photo shows signage at tanks.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335766



Photo 6: Photo shows example of marked anchors on the Location.