

Inspection Photos

3/1/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335814

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Photos also show control measures to stabilize production area and prevent off-location sediment transport during wet conditions have not been maintained in proper functioning condition.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 4: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 5: Photo shows wells on Location. .



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 6: Signage at wells



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335814



Photo 7: Photo shows example of marked anchors on the Location. Photo also shows noxious weed (Musk thistle) remnants from the 2020 growing season.

