

Final Reclamation Inspection

February 26, 2021

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 319078

Inspection Document #: 697502606

Weld County, CO

NWSE Section 28 T8N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SOONER UNIT #10-28
Location ID: 319078



Photo 1. Photo taken from the well location, facing North. Photo illustrates the Operator has performed final reclamation activities; however, there was little to no germination of desirable perennial species.



Inspection Photos

Location Name: SOONER UNIT #10-28

Location ID: 319078



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1. Much of the vegetation illustrated in the photo is a List C Colorado noxious weed, Cheatgrass.

Inspection Photos
Location Name: SOONER UNIT #10-28
Location ID: 319078



Photo 3. Photo taken from the well location, facing South. See comments under Photo 1. Photo also illustrates a List C Colorado noxious weed, Puncture vine.

Inspection Photos

Location Name: SOONER UNIT #10-28

Location ID: 319078



Photo 4. Close up photo taken from well location. Photo illustrates bare ground with no germination of desirable plant species.



Inspection Photos
Location Name: SOONER UNIT #10-28
Location ID: 319078



Photo 5. Reference photo taken west of the location, facing West.

Inspection Photos

Location Name: SOONER UNIT #10-28

Location ID: 319078



Photo 6. Photo taken from the well location, facing South. Photo illustrates the Operator has failed to reclaim the access road.