

Final Reclamation Inspection

February 26, 2021

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 330480

Inspection Document #: 697502610

Weld County, CO

SENW Section 28 T8N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SOONER UNIT #28-6-1
Location ID: 330480



Photo 1. Photo taken from the well location, facing East. Photo illustrates the Operator has performed final reclamation activities.

Inspection Photos
Location Name: SOONER UNIT #28-6-1
Location ID: 330480



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: SOONER UNIT #28-6-1
Location ID: 330480



Photo 3. Photo taken from the well location, facing South. Photo illustrates Operator has failed to reclaim the access road.

Inspection Photos
Location Name: SOONER UNIT #28-6-1
Location ID: 330480




Photo 4. 2019 aerial imagery illustrates the access road that has not been reclaimed.