

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2021

Submitted Date:

02/25/2021

Document Number:

689501118

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
,		mknop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478861	SPILL OR RELEASE	AC			-	Premium Turkey Farm PW Vault	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Inspected Facilities

Facility ID: 478861 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project No. 16538 (Form 27 Doc#402589629) was created for the removal of the produced water vault at this location.

Corrective Action: Submit a Supplemental Form 19 requesting closure of Spill ID 478861 with proceeding under an approved Form 27, as per COA in Form 19 Doc# 402556860. Date: 02/02/2021

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402611142	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361640
689501119	Field Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5361630