

Inspection Photos
Location Name: Maudlin Gulch Unit 18
Location ID: 312873



Photo 1. Overview of location taken at entrance facing north.



Photo 2. No bradenhead access apparent.

