

Inspection Photos
Location Name: Maudlin Gulch Unit 12
Location ID: 312860



Photo 1. Overview of location taken at entrance facing west.



Photo 2. No bradenhead access apparent.

