

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306




Photo 1 – Wellhead, unused Wellhead Parts



Photo 2 – Wellhead Sign



Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 3 – Unused Workover Rig Equipment



Photo 4 – Unused Workover Rig Equipment

