

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2021

Submitted Date:

03/07/2021

Document Number:

696104449

**FIELD INSPECTION FORM**

Loc ID 305545 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278982	WELL	PA	02/19/2020	OW	123-23128	MILE HIGH SHEEP 8-33	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Active.

Centralized Battery serves 2 Location IDs (306224, 305672).  
(Well(s): 2: Producing | PR).

Centralized Battery formerly served 1 Location ID (305545).  
(Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696104445 and/or Location ID #306224 for Battery / Facility, Equipment info.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 0		
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment reassigned to Location ID #306224.</a>			
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment removed.</a>			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment reassigned to Location ID #306224.</a>			
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment: <a href="#">Plugged &amp; Abandoned   PA. Equipment reassigned to Location ID #306224.</a>			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: <a href="#">Centralized Battery serves 2 Location IDs (306224, 305672).</a>					
<a href="#">Centralized Battery formerly served 1 Location ID (305545). (Well(s): 1: Plugged &amp; Abandoned   PA).</a>					
<a href="#">Refer to Field Inspection Report doc. #696104445 and/or Location ID #306224 for Battery / Facility, Equipment info.</a>					
Corrective Action:					Date:

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	0				,		
Comment:		Plugged & Abandoned   PA. Equipment reassigned to Location ID #306224.					
Corrective Action:				Date:			
<b>Paint</b>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	0				,		
Comment:		Plugged & Abandoned   PA. Equipment reassigned to Location ID #306224.					
Corrective Action:				Date:			
<b>Paint</b>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
<b>Venting:</b>							
Yes/No							
Comment:							
Corrective Action:			Date:				
<b>Flaring:</b>							
Type							
Comment:							
Corrective Action:			Date:				

**Inspected Facilities**

Facility ID: 278982 Type: WELL API Number: 123-23128 Status: PA Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 03/05/2021 at approximately 13:36 hrs. I, Bret Evins, conducted an on-site inspection at:            Operator Name: NOBLE ENERGY INC            Location Name: MILE HIGH SHEEP-66N64W /8SWSW            Location ID: 305545            Well Name: Mile High Sheep 8-33            API: 05-123-23128            Location County: Weld County, Colorado            Weather: Sunny, dry.</p> <p>While there, I observed:            Well(s): 1: Plugged &amp; Abandoned   PA.            Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (306224, 305672).            (Well(s): 2: Producing   PR).</p> <p>Centralized Battery formerly served 1 Location ID (305545).            (Well(s): 1: Plugged &amp; Abandoned   PA).</p> <p>Refer to Field Inspection Report doc. #696104445 and/or Location ID #306224 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT:            Plugged &amp; Abandoned   PA.            Well appears to be cut / capped.            Form 6 doc. #402351590 indicates plugging, cut/cap date: 02/19/2020. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/07/2021