

Final Reclamation Inspection

February 26, 2021

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 323461

Inspection Document #: 697502612

Weld County, CO

NWNE Section 28 T8N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SOONER UNIT #2-28
Location ID: 323461



Photo 1. Photo taken from the eastern well location access road, facing West. Photo illustrates the Operator has performed final reclamation activities; however, there was little to no germination of desirable perennial species. Also, stormwater BMPs are in need of maintenance, as well as fencing.



Inspection Photos
Location Name: SOONER UNIT #2-28
Location ID: 323461




Photo 2. Photo taken from the eastern well location access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: SOONER UNIT #2-28
Location ID: 323461



Photo 3. Photo taken from the eastern well location access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: SOONER UNIT #2-28
Location ID: 323461



Photo 4. Photo taken from the eastern well location access road, facing West. See comments under Photo 1.

Inspection Photos
Location Name: SOONER UNIT #2-28
Location ID: 323461



Photo 5. Photo taken from the eastern well location access road, facing West. See comments under Photo 1.