

Final Reclamation Inspection

February 26, 2021

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Location ID: 447526

Inspection Document #: 697502624

Weld County, CO

SESE Section 21 T8N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SE SEC 21 TB
Location ID: 447526



Photo 1. Photo taken from the southern tank battery location, facing North. Photo illustrates Operator has removed equipment from the northwestern corner but has failed to perform final reclamation activities.



Inspection Photos
Location Name: SE SEC 21 TB
Location ID: 447526



Photo 2. Photo taken from the southern tank battery location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SE SEC 21 TB
Location ID: 447526



Photo 3. Photo taken from the central tank battery location, facing East. Photo illustrates the majority of the location has achieved Rule 1004 vegetative standards.

