

Inspection Photos

Loc#335315

Operator: Caerus

Insp#: 692403147

Insp Date: 3/3/21





Photo#1:
Overview of Location.

March 3, 2021



Photo#2:
Interim area.



Photo#3:
Interim area.

March 3, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus GMR Loc#335315