

Inspection Photos
Location Name: Cox /22-B Pad
Location #: 442375



Photo #1
Cox 1 (05-123-41933) Wellsite
Producing | PR



Photo #2
Cox 5 (05-123-41935) Wellsite
Shut-In | SI
Workover completed.
Had parted rods.

Inspection Photos
Location Name: Cox /22-B Pad
Location #: 442375



Photo #3
Cox 5 Wellsite
Shut-In | SI
Workover rig safety signage



Photo #4
Cox 1, 5 Battery site
Active

Inspection Photos
Location Name: Cox /22-B Pad
Location #: 442375



Photo #5
Cox 1, 5 Battery site
Active
Battery signs