

Inspection Photos

API: 009-06627

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 3/3/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021

Inspection Photos



Photo 1. Facing northwest toward the location. toward the location. A power pole remains at the southwest side of the location shown at red arrow. This needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021

Inspection Photos



Photo 2. Facing east at the location. Vegetation has not re-established at the location. Soils appear to be compacted. There is a gravelly area that remains through the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021

Inspection Photos



Photo 3. Facing east at the north side of the location. The area along the fill slope is compacted and should be leveled to match the contours of the terrain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021

Inspection Photos



Photo 4. It appears mulch was applied to the soils. There is some Sandbur growing where mulch was applied but vegetation does not appear to be establishing due to compaction.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021

Inspection Photos



Photo 5. Facing west at the northeast side of the location. The fill slope has not been recontoured. The area along the fill slope is compacted and should be leveled to match the contours of the terrain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021

Inspection Photos



Photo 6. Soils are compacted at the location. Soils need to be decompacted by cross ripping to a depth of 18 inches. Compacted soil are preventing vegetation establishment. The shovel could not penetrate past 2-3 inches.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06627 | Date: 3/3/2021