

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402614166
Receive Date:
03/02/2021

Report taken by:
KRIS NEIDEL

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>WEXPRO COMPANY</u>	Operator No: <u>95960</u>	Phone Numbers
Address: <u>P O BOX 45003</u>		
City: <u>SALT LAKE CITY</u>	State: <u>UT</u>	Zip: <u>84145-0601</u>
Contact Person: <u>April Stegall</u>	Email: <u>april.stegall@dominionenergy.com</u>	
		Phone: <u>(307) 352-7561</u>
		Mobile: <u>(307) 371-3610</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 17173 Initial Form 27 Document #: 402614166

PURPOSE INFORMATION

- | | |
|----------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

Y Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>081-05569</u>	County Name: <u>MOFFAT</u>
Facility Name: <u>WILSON, F. 2</u>	Latitude: <u>40.991090</u>	Longitude: <u>-108.612980</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NENE</u>	Sec: <u>22</u>	Twp: <u>12N</u>	Range: <u>100W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>
Facility Type: <u>PIPELINE</u>	Facility ID: <u>412315</u>	API #: _____	County Name: <u>MOFFAT</u>
Facility Name: <u>HIAWATHA GATHERING PIPELINE SYSTEM 412315</u>	Latitude: _____	Longitude: _____	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: _____	Sec: _____	Twp: <u>12N</u>	Range: <u>100W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use Non-cropland, Oil and Gas

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|----------------------------------------------------------|------------------------------------------------------|---------------------------------------------------|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	GROUNDWATER	None	No groundwater encountered
Yes	SOILS	to be determined	soil analysis
No	SURFACE WATER	None	Visual inspection
No	VEGETATION	None	Visual inspection

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On 2/28/21, an operator discovered evidence of a spill (stained soil) on the surface. After investigation, it was determined that the source was a leaking buried gathering line on the well pad. The line was isolated and shut in, an emergency one call was completed and a crew was brought out to excavate the impacted material and place it on a liner in wait to be hauled to disposal.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

A composite soil sample of the impacted material was obtained, results will be submitted when recieved. After excavation of the contaminated material is finished, representative, discreet samples will be taken to confirm that all contamination has been removed.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater has not been encountered during excavation. If groundwater is encountered during excavation/remediation, COGCC will be notified immediately.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

No surface water impacts, there is no surface water in close proximity of the spill or contaminated material.

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 0
Number of soil samples exceeding 910-1 0
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) _____
-- Highest concentration of SAR _____
BTEX > 910-1 _____
Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 910-1 _____

_____ Highest concentration of Benzene (µg/l) _____
_____ Highest concentration of Toluene (µg/l) _____
_____ Highest concentration of Ethylbenzene (µg/l) _____
_____ Highest concentration of Xylene (µg/l) _____
_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) 0 Volume of liquid waste (barrels) 0

Is further site investigation required?

The extent of the impact is not known at this time. Delineation will be completed with excavation of the impacted material and reported after excavation is complete.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The leaking gathering line has been isolated and will be repaired.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Impacted material is being excavated, and placed on a liner, to be hauled to an approved disposal facility. Due to the lateral extent of the contamination, the tank on location will have to be removed temporarily to allow to equipment to excavate underneath.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____ 0

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

N/A, groundwater has not been encountered during excavation or remediation. If groundwater is encountered at any time during excavation or remediation, COGCC will be notified immediately.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other As work is completed.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Excavation of impacted material

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

soil impacted by condensate

Volume of E&P Waste (solid) in cubic yards 0

E&P waste (solid) description soil containing condensate from
leaking gathering line

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

After excavation and confirmation samples, Wexpro Company will backfill the excavation area with soil hauled in from Dickinson's gravel pit (commercial source). After the hole is backfilled to grade, the tank berm will be repaired and the tank will be re-placed. If the area needs to be seeded (outside of equipment area) the seed mix will be approved by the surface owner (BLM).

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim? Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. 02/28/2021

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/28/2021

Date of commencement of Site Investigation. _____

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Wexpro Company requests approval to continue to excavate contaminated material from the leaking gathering line site, haul to R360 disposal, remove the tank for safe excavation, backfill the excavated site with soil from Dickinson's pit after confirmation samples have been obtained and replace the tank.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: April Stegall _____

Title: Reclamation Agent _____

Submit Date: 03/02/2021 _____

Email: april.stegall@dominionenergy.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRIS NEIDEL _____

Date: 03/10/2021 _____

Remediation Project Number: 17173 _____

COA Type**Description**

	It is understood that this project is Remediation by excavation, the impacted area is not yet delineated. Careful field notes and documentation should be taken and submitted with the supplemental Form 27.
	By Rule 913.b(2)C., samples for 915-1 compliance shall be discrete not composite.
	By Rule 913.b(2)C., samples for 915-1 compliance shall be discrete not composite.
	Samples shall be for COGCC Table 915-1.
	The number of soil samples and their location should be adequate to characterize the impacted area.
	Within two weeks of approval of this document, a map showing the spill area shall be submitted. The spill area; location, observed spill area, flowpath are currently unknown.

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402614166	FORM 27-INITIAL-SUBMITTED
402614227	MAP
402614228	MAP

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

Environmental	Samples location selection should be guided by rule 915.e.(2)B.	03/10/2021
---------------	-----------------------------------------------------------------	------------

Total: 1 comment(s)