

Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335588

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 1: Photo taken from the southeast end of the Location, facing west. Photos 1-3 provide an overview of the Location from west, north to northeast.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 4: Photo of sediment trap on the northwest corner of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 5: Photo shows vegetation establishment on the interim areas of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 6: Photo of the 80 bbl produced water tank with emergency contact number.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335588



Photo 7: Photo of monitoring wells associated with Remediation project #9599

