

# Final Reclamation Inspection

March 2, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328997

Inspection Document #: 697502638

Weld County, CO

SWSE Section 15 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 1.** Photo taken from the associated offsite tank battery location, facing North. Photo illustrates the tank battery is still in use for other nearby wells.

Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 2.** Photo taken from the eastern well location access road, facing West. Photo illustrates Operator has performed final reclamation activities (i.e., seeding) with the evidence of drill rows.

Inspection Photos

Location Name: CLC RED W #15-15

Location ID: 328997



**Photo 3.** Photo taken from the eastern well location, facing Northwest. See comments under Photo 2.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697502638

Inspection Photos

Location Name: CLC RED W #15-15

Location ID: 328997



**Photo 4.** Photo taken from the eastern well location, facing West. See comments under Photo 2.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697502638

Inspection Photos  
Location Name: CLC RED W #15-15  
Location ID: 328997



**Photo 5.** Photo taken from the eastern well location, facing Southwest. See comments under Photo 2.