

# Final Reclamation Inspection

March 2, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328998

Inspection Document #: 697502640

Weld County, CO

SESE Section 15 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CLC RED W #15-16  
Location ID: 328998



**Photo 1.** Photo taken from the associated offsite tank battery location, facing North. Photo illustrates the tank battery is still in use for other nearby wells.

Inspection Photos  
Location Name: CLC RED W #15-16  
Location ID: 328998



**Photo 2.** Photo taken from the western well location access road, facing East. Photo illustrates Operator has performed final reclamation activities (i.e., seeding) with the evidence of drill rows.



Inspection Photos  
Location Name: CLC RED W #15-16  
Location ID: 328998



**Photo 3.** Photo taken from the western well location, facing East. See comments under Photo 2.

Inspection Photos  
Location Name: CLC RED W #15-16  
Location ID: 328998



**Photo 4.** Photo taken from the western well location, facing Northeast. See comments under Photo 2.